

General Environmental Incident Summary

Incident: 3674 **Date/Time Notice:** 3/3/2015 2120 **DEM Incident No:**
Responsible Party: ONEOK Rockies Midstream
Date Incident: 3/3/2015 **Time Incident:** 1700 **Duration:** 1 minutes
County: Williams **Twp:** 154 **Rng:** 99 **Sec:** 7 **Qtr:** NW SW
Lat: 48.17500 **Long:** -103.47300 **Method:** Navigation quality GPS
Location Description: Stockyards Compressor Station

Submitted By: Kim Rudningen **Affiliation:** ENV Specialist ONEOK
Address: 2700 Lincoln Ave SE
City: Sidney **State:** MT **Zip:** 59270

Received By:

Contact Person: Kim Rudningen
2700 Lincoln Ave SE
Sidney, MT 59270

Distance Nearest Occupied Building: 1 Miles **Release Contained:** Yes

Type of Incident: Tank Overflow

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 5.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Operator was filling a slip tank in the his truck bed with diesel fuel when the auto shut off failed to work. The tank overflowed onto the ground below the vehicle.

Risk Evaluation:

There are no immediate risks associated with this release.

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

There is low likelihood of impact to any surface or ground water. The spill is contained to the a small area of facility soil.

Action Taken or Planned:

Filling was immediately stopped. The opertor used absorbent pads to soak up any free standing diesel fuel. There were no offsite impacts nor impacts to surface water. Remediation will consist of removal of the topsoil and treatment with bioremediation product.

Wastes Disposal Location: Waste will be disposed of at a certified landfill.

Agencies Involved:

Updates

Date: 3/3/2015

Status: Reviewed; No Followup Required

Staff: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary, this spill was small and remained on a facility location. No followup is necessary.